Monitoring by visual inspection for river embankments managed by the national government.

## Monitoring items

	In normal times	During flooding	Immediately after flooding
River channels	<ul> <li>Deep scours in river bends and downstream of cross-sectional structures, etc.</li> <li>Tree coverage</li> <li>Sedimentation</li> </ul>		<ul> <li>Deformation of Spur dikes, stream control structures (vane works), etc</li> <li>Changes in tree coverage</li> <li>Changes in sedimentation</li> </ul>
Flood channels, low-flow revetments	• Deformation of the foundations of low-flow revetments	<ul> <li>Erosion of flood channels</li> <li>Difference in water-surface level, eddies and bubbles</li> </ul>	<ul> <li>Erosion of flood channels</li> <li>Deformation of low-flow revetments</li> <li>Fallen trees in flood channels</li> </ul>
Riverside bank slopes, high-water revetments, and levee revetments	<ul> <li>Lawn grass conditions, lawn trampling by people and animals, wheel tracks</li> <li>Cracks in bank slopes</li> <li>Deformation of anti-erosion structures (revetments, erosion-prevention sheets, etc.)</li> <li>Deformation of revetment foundations</li> <li>Scours and erosion at the joints between banks and slope roads/stairs</li> <li>Holes by moles or other small animals</li> </ul>	<ul> <li>Erosion and cracks in bank slopes</li> <li>Deformation of anti-erosion structures (revetments, erosion-prevention sheets, etc.)</li> </ul>	<ul> <li>Erosion and cracks in bank slopes</li> <li>Deformation of bank slops</li> <li>Deformation of revetments and their foundations</li> <li>Deformation of anti-erosion structures (revetments, erosion-prevention sheets, etc.)</li> <li>Deformation (erosion, etc.) around boundary areas between revetments and banks, loss of cover soil</li> </ul>
Bank crowns	<ul> <li>Cracks</li> <li>Local depressions</li> <li>Conditions of paved crown edges</li> </ul>	<ul><li>Cracks</li><li>Puddles</li><li>Erosion of paved crown edges</li></ul>	<ul><li>Cracks</li><li>Puddles</li><li>Erosion of paved crown edges</li></ul>
Landside bank slopes	<ul> <li>Lawn grass conditions, lawn trampling by people and animals, wheel tracks</li> <li>Cracks in bank slopes</li> <li>Adverse slopes and local depressions in berms (banguettes)</li> <li>Scours and erosion at the joints between banks and slope roads/stairs</li> <li>Holes by moles or other small animals</li> </ul>	<ul> <li>Deformation and Cracks in bank slopes</li> <li>Water leakage around berms</li> <li>Muddy state of bank slopes and berms</li> <li>Puddles in berms</li> </ul>	<ul> <li>Deformation and Cracks in bank slopes</li> <li>Water leakage around berms</li> <li>Muddy state of bank slopes and berms</li> <li>Puddles in berms</li> </ul>
Landside toes of banks	<ul> <li>Surface moisture content</li> <li>Local depressions</li> <li>Squeezed-out water</li> <li>Holes by moles or other small animals</li> <li>Deformation of toe protections</li> </ul>	<ul> <li>Deformation and Cracks in bank toes</li> <li>Water leakage around bank toes</li> <li>Muddy state of bank toes</li> <li>Deformation or sinking of toe protections</li> </ul>	<ul> <li>Deformation and Cracks in bank toes</li> <li>Water leakage around bank toes</li> <li>Muddy state of bank toes</li> <li>Squeezed-out water</li> <li>Deformation or sinking of toe protections</li> </ul>
Toe drains	• Deformation or sinking of drains	• Leakage or sand volcano from drain joints	• Leakage or sand volcano from drain joints
Landside areas	Surface moisture content	<ul> <li>Sand volcano around bank toes</li> <li>Land uplift and subsidence</li> </ul>	<ul> <li>Sand volcano around bank toes</li> <li>Land uplift and subsidence</li> <li>Sand volcano in paddy fields after harvesting</li> </ul>
Areas around sluice gates and other structures	<ul> <li>Deformation or cracks in attached revetments</li> <li>Gaps between structures and surrounding banks (subsidence around structures)</li> <li>Opening in joints between structures (parapet/wing walls, etc.)</li> </ul>	<ul> <li>Leakage or sand volcano around the joint parts of parapet/wing walls</li> <li>Leakage or sand volcano from the joint parts to banks</li> <li>Colour of the water in channels in landside areas</li> </ul>	<ul> <li>Leakage or sand volcano around the joint part of parapet/wing walls</li> <li>Leakage or sand volcano from the joint parts to banks</li> <li>Colour of the water in channels in landside areas</li> </ul>